


Repair Parts for Xtreme[™] 250cc (1045) Pump


406518J



Bulk Pack Replacement Parts


Ref. No.	Part No.	Description	Qty	Ref. No.	Part No.	Description	Qty
103	245232	GLAND, Packing Male (4/pack)	2	119	244999	PLUG, Throat Seal, 2.0 in.	1
104	245229	PACKING, Vee, TuffStack (10/pack)	10	119	247395	(10/pack) PLUG, Throat Seal, 2.5 in.	1
105	245230	PACKING, Vee, leather (10/pack)	4			(10/pack)	-
106	245233	GLAND, Packing Female (4/pack)		24B732	PACKING, O-ring, Filter,	2	
106a	246530	GLAND, Packing Female, yellow (4/pack)	2	123	224459	chemical resistant (10/pack) STRAINER, 60 Mesh Screen	1
109*	244893	PACKING, O-ring, Top Cylinder (10/pack)	1	123	238438	(2/pack) STRAINER, 60 Mesh Screen	
112*	244898	BALL (piston) (3/pack)	1			(25/pack)	
116*	253030	BALL (Inlet) (3/pack)	1	125*	244894	PACKING, O-ring, (10/pack)	4
117	244856	SHIM, Inlet (9/pack)	3	127*	244891	PACKING, O-ring (10/pack)	1
				128*	24B733	PACKING, O-ring chemical resistant (10/pack)	1
				135	245231	PACKING, Vee, Xtreme Seal (throat) (10/pack)	6

TuffStack [™] Repair Kit 244903
* Included with repair kit – see Bulk Pack Replacement Parts on page 1



Xtreme Seal™ and Leather Repair Kit 244853

* Included with repair kit - see Bulk Pack Replacement Parts on page 1.



All written and visual data contained in this document reflect the latest product information available at the time of publication. Graco reserves the right to make changes at any time without notice.

This manual contains English. MM 406518

Graco Headquarters: Minneapolis International Offices: Belgium, China, Japan, Korea

GRACO INC. P.O. BOX 1441 MINNEAPOLIS, MN 55440-1441

©2001, Graco Inc. is registered to ISO 9001

www.graco.com Revised 04/2010